KEY NOTES:

1. NEW SYSTEM CONNECTED SMOKE DETECTOR BELOW 2ND FLOOR STAIR LANDING. CONNECT TO EXISTING FIRE ALARM PANEL FAP-01-06, ZONE 2F66, ZU-35DS, MOD 32.
2. EXISTING SMOKE DETECTOR TO REMAIN. DISCONNECT FROM EXISTING CIRCUIT AND REMOVE EXISTING CONDUCTORS (AS NECESSARY). CONNECT TO EXISTING 2ND FLOOR CORRIDOR SMOKE DETECTOR CIRCUIT FROM FIRE ALARM PANEL FAP-01-06, ZU-35DS, MOD 32.

KEY PLAN:

HYT Corporation
FIRE PROTECTION ENGINEERS - CONSULTANTS
3496 CLAYTON ROAD - SUITE 101, CONCORD, CALIFORNIA 94519
PHONE: (925) 681-2731 * FAX: (925) 681-2733

CONSULTING FIRM

Eichleay Engineers Inc. of California
1390 Willow Pass Road, Suite 600, Concord, Ca. 94520
(925) 689-7000 • FAX (925) 689-7006
EEI JOB NO: 30330

CONSULTING FIRM

CONSULTING A/E FIRM (PRIME)

PROFESSIONAL SEAL (IF REVISION, APPLIES ONLY TO REVISED WORK)

AS BUILT
1/12/2004

ISSUE (PROGRESS, ESTIMATE, BID, CONSTRUCTION, CONFORMED, REVISION, AS-BUILT)

REVISION NUMBER	DRAWN BY	CHECKED BY	APPR'D BY	DATE	REMARKS
B	WEW	WN	MOH	1/12/04	AS BUILT
A	DWH	BBT	BBT	7/26/02	CONFORMED SET

6
SOUTH SIDE EXPANSION
FIRE ALARM, 2ND FLOOR ADDITIONS

UNIVERSITY OF CALIFORNIA
LAWRENCE BERKELEY NATIONAL LABORATORY
FACILITIES DEPARTMENT

DRAWN BY	DWH	DATE 03/1/02
CHECKED BY	BBT	5/21/02
APPROVED BY	DWH	5/21/02
CAD FILE PATH	00017554	
SCALE	1/8" = 1'-0"	
DRAWING NO.	4B06E305B	SHEET F42
PROJECT NO.	FX1080	1 OF 1