NOTES:

1. LEAVE RESISTORS CONNECTED IN FUTURE ZONE INPUTS.
2. REMOVE 15K OHM RESISTOR FROM ZONE INPUTS FOR CONNECTING PAIR CONDUCTORS FROM SITE BUILDINGS. LEAVE RESISTOR CONNECTED IN ZONE INPUTS IF THE WIRING IS NOT CONNECTED TO BUILDING FACP'S WITH CP-35 OR MXL.

PROFESSIONAL SEAL (IF REVISION, APPLIES ONLY TO REVISED WORK)	TITLE 2 CONSTRUCTION 3/8/2005	ISSUE (PROGRESS, ESTIMATE, BID, CONSTRUCTION, CONFORMED, REVISION, RECORD)	REVISION NUMBER	DRAWN BY	CHECKED BY	APPR'D BY	DATE	REMARKS

48 DIGITIZE FIRE ALARM SYST
INPUT 32 EOL AND CABLE CONNECTOR MODULE, CONNECTION DIAGRAM

UNIVERSITY OF CALIFORNIA
LAWRENCE BERKELEY NATIONAL LABORATORY
FACILITIES DIVISION

		DATE
DRAWN BY	AD	2/15/2005
CHECKED BY	MCG	3/4/2005
APPROVED BY	MCG	3/4/2005
CAD FILE PATH	00019045	
SCALE	As Noted	
DRAWING NO.	4B48E036	SHEET 1 OF 1
PROJECT NO.	FE5011	