Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
Location : 001-0401 (1 item) (Total=1)				
Work Type : PM-CC (7 items)				
1	W0241052	PM NFPA72 BLDG. 01 fire alarm system ITM (Donner Weekly)	FATSD	WASSIGN
Location : 002-0100 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0233927	Replace 106 emergency lights throughout B002 - light are not working and out of compliance. This is	FAOML	INPRG
Location : 002BR001 (1 item) (Total=1)				
Work Type : PM-CC (1 item)				
1	W0239623	PM FOR 02 BR 001 Investitgate Materials	FAOMP3	WASSIGN
Location : 002-ROF1 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0211339	Bldg. 02 PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 006-1000 (4 items) (Total=11)				
Work Type : AI (8 items)				
1	W0220898	Install gutters and unistrut supports for radiation safety shutters (RSS)	FATSE	INPRG
2	W0221723	Pull Low Volt Cable, multiple locations in ALS	FATSE	INPRG
3	W0237578	Pull low volt cables from modulators to racks	FATSE	INPRG
4	W0237765	Radiation Safety Shutters Cable Pulls	FATSE	INPRG
Work Type : PM (1 item)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0239775	PM FOR 06 BL 026, Need Breaker Panel Number	FAOMP1	WASSIGN
Work Type : PROJ (12 items)				
1	W0234298	PROJ-PMT to support LCW LOTO	FAOMP1	WASSIGN
2	W0237843	Connect temporary generators to EG-100-48 and EG-120-37 for SW-A3 work.	FATSE2	INPRG
3	W0237850	Lay down plywood for temp generator power cords at B37 and B48.	FATSC	ASSIGNED
4	W0241418	Electrical support for installation of #1 and #2 modulator. See scope of work.	FATSE	REL
Work Type : SR (6 items)				
1	W0230882	Prefab support plumbing for Modulators, install @ ALS	FATSF	WASSIGN
2	W0237013	(Child of 230882) FATSD to Bypass smoke detectors for Plumbers to solder water lines in LINAC area	FATSD	WASSIGN
Location : 006-1091 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0239771	PM FOR 06 BL 047	FAOMP1	WASSIGN
Location : 006-1999 (2 items) (Total=1)				
Work Type : PM (1 item)				
1	W0211341	Bldg. 06 PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 006-2220 (1 item) (Total=1)				
Work Type : SR (1 item)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0241388	Complete JHA google form before starting work	FATSC	SCHD
Location : 006-2270 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0238849	PM FOR 06 AHU-015 MATL at Stores	FAOMP2	WASSIGN
Location : 006-ROF1 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0219088	PM FOR 06 BL 046 3L410 1ea. MATL Here	FAOMP1	WASSIGN
Location : 015-ROF1 (1 item) (Total=2)				
Work Type : PM (2 items)				
1	W0239685	PM FOR 015 AHU-002	FAOMP1	WASSIGN
2	W0239687	PM FOR 015 AHU-001	FAOMP1	WASSIGN
Location : 017-0199 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237324	PM NFPA25 BLDG. 17/17A sprinkler ITM	FATSD	WASSIGN
Location : 027-0105C (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0239777	PM FOR 27 BL 001	FAOMP1	WASSIGN
Location : 027-0199 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237327	PM NFPA25 BLDG. 27 sprinkler ITM	FATSD	WASSIGN
Location : 030-0142 (1 item) (Total=1)				
Work Type : PM (2 items)				
1	W0238164	PM for 30 AHU005/30 BL 013	FAOMP2	WASSIGN
Location : 030-0143 (2 items) (Total=3)				
Work Type : PM (4 items)				
1	W0238160	PM for 30 AHU003/30 BL 011	FAOMP2	WASSIGN



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
2	W0238162	PM for 30 AHU004/30 BL 012	FAOMP2	WASSIGN
Work Type : SR (1 item)				
1	W0234964	Troubleshoot reoccurring trouble signal on VESDA	FATSD	WASSIGN
Location : 030-0144 (3 items) (Total=2)				
Work Type : CM-R (1 item)				
1	W0221739	Troubleshoot VESDA Power supplies reporting trouble condition	FATSD	WASSIGN
Work Type : PM (2 items)				
1	W0238110	PM for 30 AHU002/30 BL 010	FAOMP2	WASSIGN
Location : 030A-0199 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0211335	Bldg. 30 PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 031K-0199 (1 item) (Total=1)				
Work Type : SR (1 item)				
1	W0239196	Replace burnt out lamps and/or ballasts in 31K-100 / as requested by client	FAOML	WASSIGN
Location : 033-R403 (1 item) (Total=2)				
Work Type : PM (2 items)				
1	W0236866	PM for 33 ADR001	FAOMH	WASSIGN
2	W0236868	PM for 33 ADR002	FAOMH	WASSIGN
Location : 033-R405 (1 item) (Total=2)				
Work Type : PM (2 items)				
1	W0238612	PM for 33 KC 001 MATL at Stores Under W0231299	FAOMP3	WASSIGN
2	W0238614	PM for 33 KC 002 MATL at Stores Under W0231301	FAOMP3	WASSIGN



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
Location : 033U-0198X (2 items) (Total=2)				
Work Type : PM (8 items)				
1	W0237962	33U GS001 12.47kV SF6 GAS FILLED SW - GS-1-33U	FATSE2	WASSIGN
2	W0237964	33U GS002 12.47kV SF6 GAS FILLED SW - GS-2-33U	FATSE2	WASSIGN
Location : 034-0299 (1 item) (Total=1)				
Work Type : PROJ (1 item)				
1	W0239153	Open vault and escort LAMP Design into vaults A4, A5, A6	FATSE2	WASSIGN
Location : 034PIT001 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0211343	Bldg. 34 PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 037-0299 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0236016	PM for 37 CT 103	FAOMP1	WASSIGN
Location : 037-ROF1 (1 item) (Total=1)				
Work Type : PM-C (1 item)				
1	W0241163	Place Barricades Along N Rd. Parking Spaces, Night before PM for 37 CT 103	FAOMP2	WASSIGN
Location : 037TK101 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0211345	Bldg. 37 PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 043-0101 (1 item) (Total=2)				
Work Type : PM (2 items)				
1	W0236202	PM FOR 43 KC 002	FAOMP3	WASSIGN

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28

FATSE2(1 x .17)
FATSE2(1 x .17)
FATSE2(1 x 3)
FATSE2(1 x 3)
FAOMP1(1 x 1)
FAOMP1(1 x 8)
FAOMP1(1 x 8)
FAOMP1(1 x 8)
FAOMP1(1 x 8)
FAOMP1(1 x 8)
FAOMP1(1 x 8)
FAOMP1(1 x 8)
FAOMP1(1 x 8)
FAOMP1(1 x 8)
FAOMP2(1 x 1.5)
FAOMP2(1 x 1.5)
FAOMP1(1 x 1)
FAOMP3(1 x 2)

Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
2	W0236204	PM FOR 43 KC 003	FAOMP3	WASSIGN
Location : 046-0137 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0236960	Remove motor to obtain measurements, specifications, for quote	FAOMH	WASSIGN
Location : 046-0199 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237307	PM NFPA25 BLDG. 46/46A/46B/46D sprinkler ITM	FATSD	WASSIGN
Location : 047-0199 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237310	PM NFPA25 BLDG. 47 sprinkler ITM	FATSD	WASSIGN
Location : 048-0100 (2 items) (Total=1)				
Work Type : SR (1 item)				
1	W0239385	Repair outlets at B48	FATSE1	SCHD
Location : 050-4003 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0239665	Relamp 4th floor hallway lights	FAOML	WASSIGN
Location : 050-4009 (2 items) (Total=1)				
Work Type : PM (1 item)				
1	W0238199	PM FOR 50 BL 025 AX39 1ea.	FAOMP2	WASSIGN
Location : 050-4099 (2 items) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237321	PM NFPA25 BLDG. 50 sprinkler ITM	FATSD	WASSIGN
Location : 050-5002 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0239663	Relamp lights on the 5th floor hallway.	FAOML	WASSIGN
Location : 050-6059 (1 item) (Total=1)				
Work Type : CM-R (1 item)				

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28

FAOMP3(1 x 2)

FAOMH(1 x 4)
FAOMH(1 x 4)

FATSD(1 x 1)

FATSD(1 x .5)

FATSE1(1 x 8)

FAOML(1 x 2)
FAOML(1 x 2)

FAOMP2(1 x 1.5)

FATSD(1 x 1)

FAOML(1 x 2)
FAOML(1 x 2)

Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0239662	Relamp lights in the 6th floor hallway	FAOML	WASSIGN
Location : 050A-0143A (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0239701	PM FOR 50AAHU002	FAOMP2	WASSIGN
Location : 050A-0198X (2 items) (Total=1)				
Work Type : PM (3 items)				
1	W0237966	50AGS001 12.47kV SF6 GAS FILLED SW - GS-1-50A	FATSE2	WASSIGN
Location : 050A-0199 (1 item) (Total=3)				
Work Type : PM-CC (6 items)				
1	W0237313	PM NFPA25 BLDG. 50A/50C/50E sprinkler ITM	FATSD	WASSIGN
2	W0237450	PM NFPA25 BLDG. 50F preaction ITM	FATSD	WASSIGN
3	W0237453	PM NFPA25 BLDG. 50A deluge ITM	FATSD	WASSIGN
Location : 050A-2116 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0239661	Relamp 2nd floor hallway lights.	FAOML	WASSIGN
Location : 050A-2124A (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0236476	(Parent) Refresh 50A restroom entry doors at the paint shop.	FATSP	WASSIGN
Location : 050A-3122A (1 item) (Total=2)				
Work Type : CM-R (2 items)				
1	W0236477	(Parent) Refresh 50A restroom entry doors at the paint shop.	FATSP	WASSIGN
2	W0236943	(Child) Disconnect and remove 3rd floor restroom entry doors and transport to the paint shop	FATSC	WASSIGN
Location : 050A-3124A (1 item) (Total=2)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
Work Type : CM-R (2 items)				
1	W0236479	(Parent) Refresh 50A restroom entry doors at the paint shop	FATSP	WASSIGN
2	W0236944	(Child) Disconnect and remove 3rd floor restroom entry doors and transport to the paint shop	FATSC	WASSIGN
Location : 050A-4118 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0239657	Relamp 4th floor hallway lights	FAOML	WASSIGN
Location : 050A-5104 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0239797	PM FOR 50ABL 016	FAOMP2	WASSIGN
Location : 050A-5114 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0239660	Relamp 5th floor hallway lights	FAOML	WASSIGN
Location : 050A-5124A (1 item) (Total=1)				
Work Type : CM-R (2 items)				
1	W0236952	(Child) Disconnect and remove 5th floor restroom entry doors and transport to the paint shop	FATSC	ASSIGNED
Location : 050A-6105 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0239699	PM FOR 50AAHU001	FAOMP2	WASSIGN
Location : 050A-6113 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0239659	Repair 6th floor hallway lights	FAOML	WREL
Location : 050A-6134 (1 item) (Total=1)				
Work Type : PM (1 item)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0238120	PM FOR 50AAHU010 14 X 20 X 1 1ea. Pending Materials	FAOMP2	WASSIGN
Location : 050A-7101 (1 item) (Total=3)				
Work Type : PM (3 items)				
1	W0239791	PM FOR 50ABL 001	FAOMP2	WASSIGN
2	W0239793	PM FOR 50ABL 002	FAOMP2	WASSIGN
3	W0239795	PM FOR 50ABL 006	FAOMP2	WASSIGN
Location : 050A-ROF1 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0211348	Bldg. 50A PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 050B-0198X (2 items) (Total=1)				
Work Type : AI (1 item)				
1	W0233333	(PARENT) Remove CRAC 10 from server room. (2 stage work)	FATSR	ASSIGNED
Location : 050B-0299 (2 items) (Total=4)				
Work Type : PM (4 items)				
1	W0211350	Bldg. 50B PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
2	W0237968	50BGS001 12.47kV SF6 GAS FILLED SW - GS-1-50B	FATSE2	WASSIGN
Work Type : PM-CC (5 items)				
1	W0237444	PM NFPA25 BLDG. 50B preaction ITM	FATSD	WASSIGN
2	W0237447	PM NFPA25 BLDG. 50B deluge ITM	FATSD	WASSIGN
Location : 050B-1225 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0239502	Relamp lights on the 1st floor hallway	FAOML	WASSIGN
Location : 050B-1245 (1 item) (Total=2)				
Work Type : PM (2 items)				

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28

FAOMP2(1 x 1.5)

FAO

FAO

FAO

FAOMP1(1 x 1)

FATSR(1 x 4)
FATSR(1 x 4)
FATSR(1 x 4)

FAOMP1(1 x 1)

FATSE2(1 x .17)

FATSD(1 x 1)

FATSD(1 x 1)

FAOML(1 x 2)
FAOML(1 x 2)

Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0236876	PM FOR 50BAHU026 (Check if Filters & Belts Needed)	FAOMH	WASSIGN
2	W0236878	PM FOR 50BAHU027 (Check if Filters & Belts Needed)	FAOMH	WASSIGN
Location : 050B-1275 (2 items) (Total=2)				
Work Type : PM-C (2 items)				
1	W0236832	PM FOR 50B AC 011 (Order Filters & Belts)	FAOMH	WASSIGN
2	W0236834	PM FOR 50B AC 012	FAOMH	WASSIGN
Location : 050B-1299 (2 items) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237316	PM NFPA25 BLDG. 50B/50D/50F sprinkler ITM	FATSD	WASSIGN
Location : 050B-2219 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0239504	Relamp 2nd floor hallway lights	FAOML	WASSIGN
Location : 050B-2265 (1 item) (Total=2)				
Work Type : PM (3 items)				
1	W0236870	PM FOR 50BAHU036	FAOMH	WASSIGN
2	W0236872	PM for 50B AHU 040	FAOMH	WASSIGN
Location : 050B-2275 (1 item) (Total=2)				
Work Type : PM (2 items)				
1	W0236880	PM FOR 50BAHU024	FAOMH	WASSIGN
2	W0236882	PM FOR 50BAHU025	FAOMH	WASSIGN
Location : 050B-3209 (1 item) (Total=1)				
Work Type : SR (1 item)				
1	W0241402	Abate lead paint to support vendor work.	FATSP	INPRG
Location : 050B-3215 (1 item) (Total=1)				
Work Type : CM-R (1 item)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0239506	Relamp 3rd floor hallway lights	FAOML	WASSIGN
Location : 050B-4291 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0239508	Relamp 4th floor hallway lights	FAOML	WASSIGN
Location : 050B-5232 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0239509	Relamp 5th floor hallway lights.	FAOML	WASSIGN
Location : 050B-ROF1 (2 items) (Total=2)				
Work Type : PM (1 item)				
1	W0232362	PM FOR 50BAF 003 MATL at Stores	FAOMP2	WASSIGN
Work Type : SR (1 item)				
1	W0241185	Troubleshoot "Exhausto" blower motor not running	FATSE2	WASSIGN
Location : 050C-ROF1 (1 item) (Total=2)				
Work Type : PM (2 items)				
1	W0239817	PM FOR 50CBL 001	FAOMP1	WASSIGN
2	W0239819	PM FOR 50CBL 002	FAOMP1	WASSIGN
Location : 051A-0199A (1 item) (Total=1)				
Work Type : PM-CC (1 item)				
1	W0241150	(Child FATSR Support) 51A Crane Maintenance / 51-CR100 Mobile Crane	FATSR	WASSIGN
Location : 053-0008 (3 items) (Total=1)				
Work Type : PM-CC (1 item)				
1	W0237181	PM NFPA72 BLDG. 53/17/23 fire alarm system ITM	FATSD	WASSIGN
Location : 053-0101A (1 item) (Total=1)				
Work Type : SR (1 item)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0231800	Grout entryways (2) into bldg.53 second floor	FATSL	ASSIGNED
Location : 053-0199 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237330	PM NFPA25 BLDG. 53 sprinkler ITM	FATSD	WASSIGN
Location : 053B-0198 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0236842	PM FOR 53BAC 001	FAOMH	WASSIGN
Location : 054-ROF1 (2 items) (Total=5)				
Work Type : PM (4 items)				
1	W0238229	PM FOR 54 BL 002 A54 1ea. Pending Materials	FAOMP2	WASSIGN
2	W0238233	PM FOR 54 BL 010 AX26 1ea. Pending Materials	FAOMP2	WASSIGN
3	W0238237	PM FOR 54 BL 012 4L250 1ea. Pending Materials	FAOMP2	WASSIGN
4	W0238243	PM FOR 54 BL 015 B46 1ea. Pending Materials	FAOMP2	WASSIGN
Work Type : PM-CC (1 item)				
1	W0231835	PM FOR 54 ARU002	FAOMH	WASSIGN
Location : 055-0199 (2 items) (Total=3)				
Work Type : PM (2 items)				
1	W0238253	PM FOR 55 BL 027	FAOMP1	WASSIGN
2	W0238257	PM FOR 55 BL 044	FAOMP1	WASSIGN
Work Type : PM-CC (4 items)				
1	W0237336	PM NFPA25 BLDG. 55 sprinkler ITM	FATSD	WASSIGN
Location : 055-ROF1 (2 items) (Total=12)				
Work Type : PM (16 items)				

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28

FATSL(1 x 8)
FATSL(1 x 8)
FATSD(1 x 2)
FAOMH(1 x 2)
FAOMP2(1 x 1.5)
FAOMP2(1 x 1.5)
FAOMP2(1 x 1.5)
FAOMP2(1 x 1.5)
FAOMH(1 x 6)
FAOMH(1 x 6)
FAOMP1(1 x 1)
FAOMP1(1 x 1)
FATSD(1 x .5)

Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0238255	PM FOR 55 BL 029	FAOMP1	WASSIGN
2	W0238539	PM FOR 55 BL 047	FAOMP1	WASSIGN
3	W0238542	PM FOR 55 BL 045	FAOMP1	WASSIGN
4	W0238544	PM FOR 55 BL 046	FAOMP1	WASSIGN
5	W0238546	PM FOR 55 BL 013	FAOMP1	WASSIGN
6	W0238548	PM FOR 55 BL 014	FAOMP1	WASSIGN
7	W0238550	PM FOR 55 BL 018	FAOMP1	WASSIGN
8	W0238552	PM FOR 55 BL 030	FAOMP1	WASSIGN
9	W0238555	PM FOR 55 BL 033	FAOMP1	WASSIGN
10	W0238557	PM FOR 55 BL 035	FAOMP1	WASSIGN
11	W0238559	PM FOR 55 BL 039	FAOMP1	WASSIGN
12	W0238561	PM FOR 55 BL 048	FAOMP1	WASSIGN
Location : 056-0102 (1 item) (Total=1)				
Work Type : PM (3 items)				
1	W0239627	PM FOR 56 BR 003	FAOMP3	WASSIGN
Location : 056A-0121 (1 item) (Total=1)				
Work Type : PM-CC (1 item)				
1	W0237184	PM NFPA72 BLDG. 56A fire alarm system ITM	FATSD	WASSIGN
Location : 059-1003 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0211337	Bldg. 59 PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 059-1201 (3 items) (Total=5)				
Work Type : CM-R (1 item)				
1	W0241141	Remove and replace VFD-014	FATSE2	WASSIGN
Work Type : PM-CC (8 items)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0237274	PM NFPA25 BLDG. 59 FRA001 sprinkler ITM	FATSD	WASSIGN
2	W0237277	PM NFPA25 BLDG. 59 FRA002 sprinkler ITM	FATSD	WASSIGN
3	W0237280	PM NFPA25 BLDG. 59 FRA003 sprinkler ITM	FATSD	WASSIGN
4	W0237283	PM NFPA25 BLDG. 59 FRA004 sprinkler ITM	FATSD	WASSIGN
Location : 059-3052 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0241139	Relamp break room and stairwell lights	FAOML	WASSIGN
Location : 059-5999 (1 item) (Total=2)				
Work Type : CM-R (2 items)				
1	W0230625	(Parent) Remove and replace return air sensor and controller per troubleshooting findings.	FAOMH	WASSIGN
2	W0239403	(Child) Provide support for return air sensor replacement (59-RTU-003)	FMCS	WASSIGN
Location : 060-0199 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237270	PM NFPA25 BLDG. 60/63/55A sprinkler ITM	FATSD	WASSIGN
Location : 060-0199X (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0237928	Building Roll Up Door PM Bldg. 60	FATSE2	WASSIGN
Location : 062-0033 (3 items) (Total=1)				
Work Type : PM (3 items)				
1	W0211352	Bldg. 62/62F PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 062-0099 (2 items) (Total=1)				
Work Type : PM (1 item)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0237988	PM for 62 PNL064	FATSE2	WASSIGN
Location : 062-0101 (1 item) (Total=2)				
Work Type : PM (2 items)				
1	W0224629	PM 62 AHU002: SCHD SCISSOR LIFT, REQUIRED (Carbons) MATL Here	FAOMP1	WASSIGN
2	W0224631	PM 62 AHU003: SCHD SCISSOR LIFT, REQUIRED (Carbons) MATL Here	FAOMP1	WASSIGN
Location : 062-0198X (2 items) (Total=4)				
Work Type : PM (8 items)				
1	W0237887	PM for 62 ADF002	FATSE2	WASSIGN
2	W0238020	Transformer Semi-Annual Job Plan	FATSE2	WASSIGN
3	W0237970	62 GS001 12.47kV SF6 GAS FILLED SW - GS-1-62	FATSE2	WASSIGN
4	W0237972	62 GS002 12.47kV SF6 GAS FILLED SW - GS-2-62	FATSE2	WASSIGN
Location : 062-0202 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0237932	Building Handicap Door PM Bldg. 062	FATSE2	WASSIGN
Location : 064-0160 (1 item) (Total=2)				
Work Type : PM (2 items)				
1	W0236896	PM FOR 64 DSRO 002	FAOMH	REL
2	W0236898	PM FOR 64 DSRO 003	FAOMH	REL
Location : 064-0195 (2 items) (Total=1)				
Work Type : SR (1 item)				
1	W0234981	Troubleshoot Ground Fault on FACP	FATSD	WASSIGN
Location : 064-0199 (4 items) (Total=1)				
Work Type : PM-CC (3 items)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0237348	PM NFPA25 BLDG. 64/56 sprinkler ITM	FATSD	WASSIGN
Location : 064-0199X (3 items) (Total=2)				
Work Type : CM-R (2 items)				
1	W0238930	(Child) Perform oil sample and verify operation of circuit B	FAOMH	WASSIGN
Work Type : PM (1 item)				
1	W0236900	PM FOR 64 DSRO 004	FAOMH	WASSIGN
Location : 064C-0199 (2 items) (Total=1)				
Work Type : PM (3 items)				
1	W0237980	71 GS 003 12.47kV SF6 GAS FILLED SW - GS-3-71	FATSE2	WASSIGN
Location : 064-ROF1 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0236894	PM FOR 64 DSRO 001	FAOMH	WASSIGN
Location : 065-0022 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0241122	Repair basement hallway lights	FAOML	WASSIGN
Location : 065-0199 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237351	PM NFPA25 BLDG. 65/65A/65B sprinkler ITM	FATSD	WASSIGN
Location : 066-0110 (2 items) (Total=3)				
Work Type : PM-CC (1 item)				
1	W0228480	PM FOR 66 BR 003 MATL at Stores	FAOMP3	WASSIGN
Work Type : PROJ (2 items)				
1	W0236688	LOTO Support for contractor work	FATSE2	WASSIGN
2	W0236689	LOTO Support for contractor work	FATSE2	WASSIGN
Location : 067-1107 (1 item) (Total=1)				
Work Type : PM-C (1 item)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0230962	PM 67HU002 (Wait for High Humidity/Foggy Day)	FAOMH	WASSIGN
Location : 067-4110 (1 item) (Total=1)				
Work Type : SR (1 item)				
1	W0217676	Troubleshoot Door Holder, on 4th floor, not working.	FATSD	WASSIGN
Location : 067-6209 (1 item) (Total=1)				
Work Type : CM-P (1 item)				
1	W0237641	HVAC to support FMCS	FAOMH	WASSIGN
Location : 067A-0102 (3 items) (Total=1)				
Work Type : PM (1 item)				
1	W0211356	Bldg. 67A PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 067A-0201 (2 items) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0239625	PM FOR 67ABR 005	FAOMP3	WASSIGN
Location : 067-ROF1 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0211354	Bldg. 67 PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 068-0101 (1 item) (Total=2)				
Work Type : PM-CC (11 items)				
1	W0237187	PM NFPA72 BLDG. 68 fire alarm system ITM	FATSD	WASSIGN
2	W0237498	PM NFPA25 BLDG. 68 grid booster pump ITM (weekly)	FATSD	WASSIGN
Location : 068-0199 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237360	PM NFPA25 BLDG. 68/75F sprinkler ITM	FATSD	WASSIGN
Location : 068TK001 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28

FAOMH(1 x 4)
FATSD(1 x 2)
FATSD(1 x 2)
FAOMH(1 x 3)
FAOMP1(1 x 1)
FAOMP3(1 x 2)
FAOMP1(1 x 1)
FATSD(1 x 2)
FATSD(1 x 2)
FATSD(1 x 1)
FATSD(1 x 2)

Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0237483	PM NFPA25 BLDG. 68 water storage tank ITM	FATSD	WASSIGN
Location : 070-0103 (1 item) (Total=1)				
Work Type : CM-R (2 items)				
1	W0236626	Troubleshoot fume hood flow issues	FAOMH	WASSIGN
Location : 070-0177 (1 item) (Total=1)				
Work Type : SR (1 item)				
1	W0239371	Space too cold; troubleshoot heating and cooling for the space.	FAOMH	WASSIGN
Location : 070-0183A (1 item) (Total=2)				
Work Type : PM (2 items)				
1	W0240087	PM FOR 70 BL 128	FAOMP1	WASSIGN
2	W0240089	PM FOR 70 BL 129	FAOMP1	WASSIGN
Location : 070-0199 (3 items) (Total=4)				
Work Type : CM-R (1 item)				
1	W0241462	Complete JHA google form before starting work	FATSC	SCHD
Work Type : PM (6 items)				
1	W0237974	70 GS003 12.47kV SF6 GAS FILLED SW - GS-3-70	FATSE2	WASSIGN
2	W0237976	70 GS004 12.47kV SF6 GAS FILLED SW - GS-4-70	FATSE2	WASSIGN
Work Type : PM-CC (3 items)				
1	W0237369	PM NFPA25 BLDG. 70 sprinkler ITM	FATSD	WASSIGN
Location : 070A-1109 (1 item) (Total=1)				
Work Type : SR (1 item)				
1	W0228973	Remove and replace freezer evaporator coil.	FAOMH	WASSIGN
Location : 070A-1115A (1 item) (Total=1)				
Work Type : PM (2 items)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0236844	PM FOR 70AAC 004	FAOMH	WASSIGN
Location : 070A-1199 (1 item) (Total=1)				
Work Type : PM-CC (3 items)				
1	W0237366	PM NFPA25 BLDG. 70A sprinkler ITM	FATSD	WASSIGN
Location : 070A-3329 (3 items) (Total=7)				
Work Type : PM (1 item)				
1	W0211358	Bldg. 70/70A PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Work Type : PM-C (4 items)				
1	W0239592	(Child FATSE) PM FOR 70AARU001	FATSE1	WASSIGN
2	W0239594	(Child FATSF) PM FOR 70AARU001	FATSF	WASSIGN
3	W0239604	(Child FATSF) PM FOR 70AARU004	FATSF	WASSIGN
4	W0239606	(Child FATSE) PM FOR 70AARU004	FATSE1	WASSIGN
Work Type : PM-CC (3 items)				
1	W0231823	(Parent) PM FOR 70AARU001	FAOMH	WASSIGN
2	W0231827	(Parent) PM FOR 70AARU004 (Material Here per Tony)	FAOMH	WASSIGN
Location : 070A-4475 (1 item) (Total=1)				
Work Type : AI (1 item)				
1	W0239445	Remove 208V circuit & receptacle and replace with 120V circuit & receptacle	FATSE1	WASSIGN
Location : 070A-ROF1 (3 items) (Total=3)				
Work Type : CM-R (2 items)				

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28

FAOMH(1 x 3)
FAOMH(1 x 3)
FATSD(1 x .5)
FAOMP1(1 x 1)
FATSE1(1 x 2)
FATSE1(1 x 2)
FATSE1(1 x 2)
FATSE1(1 x 2)
FATSF(1 x 5)
FATSF(1 x 5)
FATSF(1 x 5)
FATSF(1 x 5)
FATSF(1 x 5)
FATSF(1 x 5)
FATSF(1 x 5)
FATSF(1 x 5)
FATSE1(1 x 2)
FATSE1(1 x 2)
FATSE1(1 x 2)
FATSE1(1 x 2)
FAOMH(1 x 8)
FAOMH(1 x 8)
FAOMH(1 x 8)
FAOMH(1 x 8)
FAOMH(1 x 8)
FAOMH(1 x 8)
FAOMH(1 x 8)
FAOMH(1 x 8)
FATSE1(1 x 8)
FATSE1(1 x 8)

Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0229446	Repair kinked differential pressure line.	FAOMH	WASSIGN
2	W0241466	Gather materials list for insulation repair	FATSF	SCHD
Work Type : PM (1 item)				
1	W0236846	PM FOR 70AAC 005	FAOMH	WASSIGN
Location : 071-0002A (1 item) (Total=1)				
Work Type : SR (1 item)				
1	W0232013	Replace burnt out lamps and or/ballasts as requested by the customer/client. See long text for more	FAOML	WASSIGN
Location : 071-0121 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0228470	PM FOR 71 BR 006 MATL at Stores	FAOMP3	WASSIGN
Location : 071-0199 (3 items) (Total=6)				
Work Type : PM (8 items)				
1	W0237889	PM for 71 ADF001	FATSE2	WASSIGN
2	W0238589	PM for TRW filter 71 FL 002 2/22 - 2/28	FAOMP3	WASSIGN
3	W0238597	PM for TRW filter 71 FL 003 2/22 - 2/28	FAOMP3	WASSIGN
4	W0237978	71 GS 002 12.47kV SF6 GAS FILLED SW - GS-2-71	FATSE2	WASSIGN
Work Type : PM-CC (4 items)				
1	W0237375	PM NFPA25 BLDG. 71/71B sprinkler ITM	FATSD	WASSIGN
2	W0237459	PM NFPA25 BLDG. 71 preaction ITM	FATSD	WASSIGN
Location : 071-0208 (1 item) (Total=1)				
Work Type : SR (1 item)				
1	W0235001	Troubleshoot the Trouble signal on the FACP	FATSD	WASSIGN



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
Location : 071C-0199 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237372	PM NFPA25 BLDG. 71T/J/C/P/F/K/D trailers sprinkler ITM	FATSD	WASSIGN
Location : 071-ROF1 (2 items) (Total=1)				
Work Type : PM (1 item)				
1	W0211360	Bldg. 71 PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 072-FL1 (1 item) (Total=1)				
Work Type : SR (1 item)				
1	W0234837	HVAC to investigate AC -10 in B72 tripped	FAOMH	WASSIGN
Location : 074-0198X (1 item) (Total=2)				
Work Type : PM (6 items)				
1	W0237982	EC GS001 12.47kV SF6 GAS FILLED SW - GS-1-EC	FATSE2	WASSIGN
2	W0237984	EC GS002 12.47kV SF6 GAS FILLED SW - GS-2-EC	FATSE2	WASSIGN
Location : 075-0199 (2 items) (Total=3)				
Work Type : PM (4 items)				
1	W0237903	PM for 69 ADF002	FATSE2	WASSIGN
2	W0237998	PM for 69 PNL010	FATSE2	WASSIGN
3	W0238034	PM for 69 XFM217	FATSE2	WASSIGN
Location : 076-0129A (1 item) (Total=1)				
Work Type : SR (1 item)				
1	W0229577	HVAC to complete Refrigerant reports for the EPA 2 days per month	FAOMH	INPRG
Location : 076-0199 (2 items) (Total=1)				
Work Type : PM (4 items)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0239616	B76 Fuel Spill Containment Basin 2/22 - 2/28	FAOMP3	WASSIGN
Location : 076-0223C (1 item) (Total=1)				
Work Type : SR (1 item)				
1	W0239294	Replace burnt-out lights & ballasts in 2nd floor restrooms (men 76-223C) & (women 76-223A)	FAOML	SCHD
Location : 077-0108 (1 item) (Total=1)				
Work Type : PM-C (1 item)				
1	W0235011	PM FOR 77 AHU037 - UMF (Coordinated Per email Confermation with Fam & Occupants)	FAOMH	WASSIGN
Location : 077-0123 (1 item) (Total=1)				
Work Type : PM (2 items)				
1	W0240422	(Child FATSR Support) BLDG 77 Crane Maintenance (Sched for 2/23)	FATSR	WREL
Location : 077-0123A (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0239933	PM FOR 77 BL 048	FAOMP2	WASSIGN
Location : 077-0123B (1 item) (Total=2)				
Work Type : PM (2 items)				
1	W0239935	PM FOR 77 BL 049	FAOMP2	WASSIGN
2	W0239939	PM FOR 77 BL 052	FAOMP2	WASSIGN
Location : 077-0125 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0239937	PM FOR 77 BL 050	FAOMP2	WASSIGN
Location : 077-0141C (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0239941	PM FOR 77 BL 053	FAOMP2	WASSIGN

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28

FAOMP3(1 x .5)

FAOML(1 x 2)
FAOML(1 x 2)

FAOMH(1 x 3)

FATSR(1 x 4)
FATSR(1 x 4)
FATSR(1 x 4)
FATSR(1 x 4)
FATSR(1 x 4)
FATSR(1 x 4)

FAOMP2(1 x 1)

FAOMP2(1 x 1)

FAOMP2(1 x 1)

FAOMP2(1 x 1)

FAOMP2(1 x 1)

Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
Location : 077-0199 (3 items) (Total=1)				
Work Type : SR (1 item)				
1	W0239651	FATSL - Clear clog in storm drain outside B77 -108	FATSL	SCHD
Location : 077-0199X (1 item) (Total=1)				
Work Type : PM (6 items)				
1	W0236928	PM FOR 77 RF 004	FAOMH	WASSIGN
Location : 077-0240 (2 items) (Total=1)				
Work Type : PM (1 item)				
1	W0239919	PM FOR 77 BL 024	FAOMP2	WASSIGN
Location : 077-0244A (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0239943	PM FOR 77 BL 054	FAOMP2	WASSIGN
Location : 077-0244B (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0239945	PM FOR 77 BL 055	FAOMP2	WASSIGN
Location : 077A-0103 (1 item) (Total=1)				
Work Type : PM-CC (1 item)				
1	W0240470	PM NFPA72 BLDG. 77A fire alarm system ITM	FATSD	WREL
Location : 077-ROF1 (1 item) (Total=2)				
Work Type : PM (2 items)				
1	W0238852	PM FOR 77 AHU028 MATL at Stores	FAOMP1	WASSIGN
2	W0238854	PM FOR 77 AHU036 MATL at Stores	FAOMP1	WASSIGN
Location : 077-SKID (4 items) (Total=3)				
Work Type : CM-R (2 items)				
1	W0207331	(Parent) Prepare chiller ARU004 for vendor Retubing and Provide vendor support as needed	FAOMH	INPRG
Work Type : PM (2 items)				

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28

FATSL(1 x 4)

FAOMH(1 x 1)
FAOMH(1 x 1)

FAOMP1(1 x 1)

FAOMP2(1 x 1)

FAOMP2(1 x 1)

FATSD(1 x 1)

FAOMP1(

FAOMP1(1 x 3.5)

FAOMH(1 x 4) FAOMH(1 x 4) FAOMH(1 x 4) FAOMH(1 x 4) FAOMH(1 x 4)

Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0238575	PM ON 77 FL001 (PEP IMF Water Filter, Sand) FEB	FAOMP1	WASSIGN
2	W0238579	PM ON 77 FL002 (PEP IMF Water Filter, Sand) FEB	FAOMP1	WASSIGN
Location : 081-0199 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237405	PM NFPA25 BLDG. 81 sprinkler ITM	FATSD	WASSIGN
Location : 082-0100 (1 item) (Total=2)				
Work Type : PM-CC (11 items)				
1	W0237408	PM NFPA25 BLDG. 82 sprinkler ITM	FATSD	WASSIGN
2	W0237510	PM NFPA25 BLDG. 82 grid booster pump ITM (weekly)	FATSD	WASSIGN
Location : 082TK002 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237486	PM NFPA25 BLDG. 82 water storage tank ITM	FATSD	WASSIGN
Location : 083-0110 (1 item) (Total=3)				
Work Type : AI (3 items)				
1	W0229180	FATSF to upsize pipe diameter of DCW Main water supply to increase water pressure	FATSF	WASSIGN
2	W0236941	(CHILD of W0229180) PMT's to isolate, LOTO and shutoff City Water valve going into building	FAOMP1	WASSIGN
3	W0237727	Fire Alarm to bypass smoke detectors to allow Plumbers to do repair.	FATSD	WASSIGN
Location : 083-0150 (3 items) (Total=6)				
Work Type : CM-R (6 items)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0234484	PMT's to remove old motor & replace with a new one	FAOMP1	WASSIGN
2	W0238927	PMT's to remove old motor & replace with a new one	FAOMP1	WASSIGN
3	W0238939	(CHILD of W0238927) FATSE2 to provide LOTO support for KC 002 Motor that's Locked Up	FATSE2	WASSIGN
4	W0238942	(CHILD of W0234484) FATSE2 to provide LOTO support for KC 001 Motor that's Locked Up	FATSE2	WASSIGN
5	W0239004	LOTO, remove and replace motor overload heaters	FATSE2	WASSIGN
6	W0239005	(CHILD of W0239004) PMT's to provide LOTO by shutting down equipment to MCC before power is cut	FAOMP1	WASSIGN
Location : 083-0199 (1 item) (Total=1)				
Work Type : PM-CC (3 items)				
1	W0239554	PM FOR 83 BFP003	FAOMP1	WASSIGN
Location : 083-0199X (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0239558	PM FOR 83 EQV001	FAOMP1	WASSIGN
Location : 083-ROF1 (2 items) (Total=1)				
Work Type : SR (1 item)				
1	W0238641	FAOMH to Replace contactors for compressor and condenser fan motor for 83 ARU002	FAOMH	WASSIGN
Location : 084-0104 (1 item) (Total=1)				
Work Type : PM (1 item)				

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28

FAOMP1(1 x 4)
FAOMP1(1 x 4)
FATSE2(1 x 2)
FATSE2(1 x 2)
FATSE2(1 x 2)
FATSE2(1 x 2)
FATSE2(1 x 4)
FATSE2(1 x 4)
FAOMP1(1 x 1)
FAOMP1(1 x 1)
FAOMP1(1 x 2)
FAOMP1(1 x 1.83)
FAOMH(1 x 4)

Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0227958	PM for 84 MP 001 MATL at Stores	FAOMP2	WASSIGN
Location : 084-0199 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0240294	PM FOR 84 BFP005	FAOMP2	WASSIGN
Location : 084-0375 (2 items) (Total=1)				
Work Type : SR (1 item)				
1	W0231598	MM - Clock needs to be fixed to right time FEE	FAOML	WASSIGN
Location : 084B-0091 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0211362	Bldg. 84/84B PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 084B-0092 (2 items) (Total=1)				
Work Type : PM-CC (5 items)				
1	W0240292	PM FOR 84 BFP002	FAOMP2	WASSIGN
Location : 084-ROF1 (1 item) (Total=2)				
Work Type : CM-R (2 items)				
1	W0224555	PMT's to remove old motor & replace with a new one	FAOMP1	WASSIGN
2	W0233262	FATSE2 to provide LOTO support for motor replacement	FATSE2	WASSIGN
Location : 085-0118 (2 items) (Total=2)				
Work Type : SR (2 items)				
1	W0235309	Cut Existing anchors and seismically anchor new freezer	FATSC	WASSIGN
2	W0238935	Move new freezer into place next to Freezer A	FATSR	ASSIGNED
Location : 085-0199 (3 items) (Total=1)				
Work Type : PM (2 items)				
1	W0239164	Weekly PM test of 85 ALT 096 2/22 - 2/28	FAOMP3	WASSIGN
Location : 085E-ROF1 (1 item) (Total=2)				



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
Work Type : CM-R (2 items)				
1	W0237039	PMT's to install repair kit for BFP-Failed test & re-test once install complete	FAOMP1	WASSIGN
2	W0238893	Bypass Fire Alarm system for PMT BFP Testing/Repair	FATSD	WASSIGN
Location : 085H-0199 (1 item) (Total=2)				
Work Type : CM-R (2 items)				
1	W0237041	PMT's to install repair kit for BFP-Failed test & re-test once install complete	FAOMP1	WASSIGN
2	W0238899	Bypass Fire Alarm system for PMT BFP Testing/Repair	FATSD	WASSIGN
Location : 088-0096 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0160731	(PARENT) Remove and replace exterior door to room 096 with Security and Emergency services support.	FATSC	WREL
Location : 088-0199 (2 items) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237432	PM NFPA25 BLDG. 88/88B/88C/88D sprinkler ITM	FATSD	WASSIGN
Location : 088-0199X (1 item) (Total=7)				
Work Type : PM (7 items)				
1	W0237891	PM for 88 ADF002	FATSE2	WASSIGN
2	W0237893	PM for 88 ADF003	FATSE2	WASSIGN
3	W0237895	PM for 88 ADF004	FATSE2	WASSIGN
4	W0237990	PM for 88 PNL152	FATSE2	WASSIGN
5	W0237992	PM for 88 PNL153	FATSE2	WASSIGN

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28



Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
6	W0238024	PM for 88 XFM080	FATSE2	WASSIGN
7	W0238026	PM for 88 XFM198	FATSE2	WASSIGN
Location : 088CGT001 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0211332	Bldg. 88 PM Monthly Vibration Survey by Vendor	FAOMP1	WASSIGN
Location : 090-0027A (1 item) (Total=1)				
Work Type : PM (3 items)				
1	W0235948	PM FOR 90 BL 007 MATL at Stores	FAOMP2	WASSIGN
Location : 090-0096 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0236858	PM FOR 90 AC 032 (Carbon Filter)	FAOMH	WASSIGN
Location : 090-0099 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237435	PM NFPA25 BLDG. 90/90C/90P sprinkler ITM	FATSD	WASSIGN
Location : 090-1099 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0236852	PM FOR 90 AC 029	FAOMH	WASSIGN
Location : 090-4035 (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0235942	PM FOR 90 BL 004 MATL at Stores	FAOMP2	WASSIGN
Location : 090-4047 (1 item) (Total=2)				
Work Type : PM (2 items)				
1	W0235944	PM FOR 90 BL 005 MATL at Stores	FAOMP2	WASSIGN
2	W0235946	PM FOR 90 BL 006 MATL at Stores	FAOMP2	WASSIGN
Location : 090-4049A (1 item) (Total=1)				
Work Type : PM (1 item)				

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28

FATSE2(1 x 1)
FATSE2(1 x 1)
FAOMP1(1 x 1)
FAOMP2(1 x 2)
FAOMH(1 x 2)
FAOMH(1 x 2)
FATSD(1 x .5)
FAOMH(1 x 1.5)
FAOMH(1 x 1.5)
FAOMP2(1 x 2)
FAOMP2(1 x 2)
FAOMP2(1 x 2)

Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0235936	PM FOR 90 BL 001 MATL at Stores	FAOMP2	WASSIGN
Location : 090-4049B (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0235938	PM FOR 90 BL 002 MATL at Stores	FAOMP2	WASSIGN
Location : 090-4049C (1 item) (Total=1)				
Work Type : PM (1 item)				
1	W0235940	PM FOR 90 BL 003 MATL at Stores	FAOMP2	WASSIGN
Location : 090C-0106 (1 item) (Total=1)				
Work Type : CM-R (1 item)				
1	W0239205	Trailer is too cold; troubleshoot heating and cooling for the space.	FAOMH	WASSIGN
Location : 090-ROF1 (1 item) (Total=2)				
Work Type : PM (3 items)				
1	W0236850	PM FOR 90 AC 028 (Carbon Filter)	FAOMH	WASSIGN
2	W0236854	PM FOR 90 AC 030 (Carbon Filter)	FAOMH	WASSIGN
Location : 090X-0101 (2 items) (Total=2)				
Work Type : PM-CC (2 items)				
1	W0237465	PM NFPA25 BLDG. 90X sprinkler ITM	FATSD	WASSIGN
Work Type : SR (2 items)				
1	W0239400	Transport (1)65 foot boom lift and (1)scissor lift for training scheduled on 2/8/21	FATSR	ASSIGNED
Location : 091-0192 (1 item) (Total=1)				
Work Type : PM-CC (2 items)				
1	W0237468	PM NFPA25 BLDG. 91 sprinkler ITM	FATSD	WASSIGN
Location : 091U-0101 (3 items) (Total=3)				
Work Type : PM-CC (2 items)				

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28

FAOMP2(1 x 2)

FAOMP2(1 x 2)

FAOMP2(1 x 2)

FAOMH(1 x 4)
FAOMH(1 x 4)

FAOMH(1 x 1.5)
FAOMH(1 x 1.5)

FAOMH(1 x 2)
FAOMH(1 x 2)

FATSD(1 x .5)

FATSR(1 x 4)
FATSR(1 x 4)
FATSR(1 x 4)

FATSD(1 x .5)

Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
1	W0237471	PM NFPA25 BLDG. 91U sprinkler ITM	FATSD	WASSIGN
Work Type : SR (3 items)				
1	W0234831	91U-ARU-001 Investigate adding of head pressure control valve on TW piping (Schedule w/HVAC ChildWO)	FMCS	WASSIGN
2	W0236958	HVAC support w/ 91U-ARU-001: Investigate addition of head pressure control valve on TW piping	FAOMH	SCHD
Location : 37CT103 (1 item) (Total=2)				
Work Type : CM-R (2 items)				
1	W0241161	FATSL - Traffic monitor/control for FAOMP1 while working on B37 CTW. 2/23 - 2/24	FATSL	ASSIGNED
2	W0241183	Traffic monitor/control for FAOMP1 while working on B37 CTW.	FATSL	ASSIGNED
Location : 977-0120K (1 item) (Total=1)				
Work Type : SR (1 item)				
1	W0239358	Laborers to vacuum trailer - ecopod lysmiter (big cylinder units with dirt to be vacuum out.	FATSL	ASSIGNED
Location : H (1 item) (Total=15)				
Work Type : PM (15 items)				
1	W0240772	NORTH FORK B071	FATSL	ASSIGNED
2	W0240774	NORTH FORK B090, B081-B082	FATSL	ASSIGNED
3	W0240776	NORTH FORK B055	FATSL	ASSIGNED
4	W0240778	NORTH FORK B056	FATSL	ASSIGNED

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28

FATSD(1 x 5)
FMCS(1 x 4)
FAOMH(1 x 4)
FAOMH(1 x 4)
FATSL(1 x 8)
FATSL(1 x 8)
FATSL(1 x 8)
FATSL(1 x 8)
FATSL(1 x 4)
FATSL(1 x 4)
FATSL(1 x 14)
FATSL(1 x 14)
FATSL(1 x 12)
FATSL(1 x 12)
FATSL(1 x 6)
FATSL(1 x 6)
FATSL(1 x 4)
FATSL(1 x 4)

Work - Standard | 702 rows

	Work Order #	Description	Lead Cr	Status
5	W0240780	NORTH FORK BLACKBERRY CANYON PARK LOT	FATSL	ASSIGNED
6	W0240782	NORTH FORK B064	FATSL	ASSIGNED
7	W0240784	NORTH FORK B051 FIRE TRAIL	FATSL	ASSIGNED
8	W0240786	NORTH FORK B050 AND SUBSTATION	FATSL	ASSIGNED
9	W0240788	NORTH FORK B070	FATSL	ASSIGNED
10	W0240790	NORTH FORK B088	FATSL	ASSIGNED
11	W0240792	NORTH FORK B017 AND V-DITCHES	FATSL	ASSIGNED
12	W0240794	NORTH FORK B046	FATSL	ASSIGNED
13	W0240796	NORTH FORK B058	FATSL	ASSIGNED
14	W0240798	NORTH FORK B002	FATSL	ASSIGNED
15	W0240800	NORTH FORK B007	FATSL	ASSIGNED
Location : HSITE30 (1 item) (Total=1)				
Work Type : PM (3 items)				
1	W0237960	Gas Switch Carb Report PM (Parent with Routes)	FATSE2	WASSIGN
Location : HSITE40 (2 items) (Total=1)				
Work Type : CM-R (1 item)				
1	W0237591	Repair lights on walkway between B2 and B23.	FAOML	SCHD
Location : HSITE4010 (2 items) (Total=1)				
Work Type : PROJ (1 item)				
1	W0229640	Remove light control modules and replace with Encelium Control Nodes	FAOML	INPRG

Feb 21

Mon	Tue	Wed	Thu	Fri	Sat	Sun
22	23	24	25	26	27	28



Craft - Resource Availability | 20 rows

	Craft	Feb 21						
		Mon	Tue	Wed	Thu	Fri	Sat	Sun
		22	23	24	25	26	27	28
1	FMCS	16	16	16	16	8		
2	FATSR	-2	-8	-8	16	16		
3	FATSP	-4	-4	4	4	4		
4	FATSL	-241	0	-8	12	0		
5	FATSF	2	10	-2	10	18		
6	FATSE2	-8.95	-3.2	-7.37	-5.2	-1.2		
7	FATSE1	15.2	23.2	31.2	31.2	35.2		
8	FATSE	-15.6	8.4	-15.6	-23.6	-23.6	-8	-8
9	FATSD	-2.8	-8.8	-4.8	-6.8	-3.8		
10	FATSC	8	30	16	28	28		
11	FASVO							
12	FASVM	22	30	30	30	22	8	8
13	FAPOW							
14	FAOMP3	19	27.5	26	31.5	28	12	6
15	FAOMP2	7.5	24	12	10	-3.5	2	9.5
16	FAOMP1	12	11	4	8.67	9.2	15.8	10.5
17	FAOMP							
18	FAOML	0	0	3	1	16	-32	